4-Point inspection Form			
Insured/Applicant Name: Canterbury at Aberdeen Condo Assoc.	Application / Policy #:		
Address Inspected: 8034 Aberdeen Dr, Boynton Beach, FL 33472			
Actual Year Built: 1997	Date Inspected: 03/06/2023		
Minimum Photo Requirements			
☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, t	under cabinet plumbing/drains, exposed valves		
☑ Main electrical service panel with interior door label			
☑ Electrical box with panel off			
☑ All hazards or deficiencies noted in this report			
A Florida-licensed inspector must	complete, sign and date this form.		
	, or a similar form, that is obtained from the Florida licensed professional of ot a warranty or assurance of the suitability, fitness or longevity of any of the		
<b>Electrical System</b> Separate documentation of any aluminum wiring remediation must be provi	ded and certified by a licensed electrician.		
Main Panel	Second Panel		
Type: ☑ Circuit breaker ☐ Fuse	Type: ☑ Circuit breaker ☐ Fuse		
Total Amps: 150 Is amperage sufficient for current usage?   ✓ Yes □ No (explain)	Total Amps: <u>150</u> Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)		
is amperage sufficient for current usage? ▶ Yes ☐ No (explain)	is amperage sufficient for current usage? 🗷 Yes 🗀 No (explain)		
Indicate presence of any of the following:			
☐ Cloth wiring			
☐ Active knob and tube			
$\square$ Branch circuit aluminum wiring (If present, describe the usage of all al	uminum wiring):		
* If single strand (aluminum branch) wiring, provide details of all remediati	on. Separate documentation of all work must be provided.		
☐ Connections repair via COPALUM crimp			
☐ Connections repair via AlumniConn			
Hazards Present	☐ Double taps		
☐ Blowing fuses	□ Exposed wiring		
☐ Tripping breakers	☐ Unsafe wiring		
☐ Empty sockets	☐ Improper breaker size		
	□ Scoring		
☐ Loose Wiring	☐ Other (explain)		
☐ Improper grounding	□ Other (explain)		
□Corrosion			
☐ Over fusing			
General condition of the electrical system:   ☑ Satisfactory □ Unsatisfactory	ctory (explain)		
Supplemental information			

Second Panel

Panel age: 2010

Year last updated: 2010

Brand/Model: General Electric

Wiring Type

☑ Copper

☑ NM, BX or Conduit

South Florida Inspectors 03/06/2023

Main Panel

Panel age: <u>1997</u>

Year last updated: 1997

Brand/Model: General Electric

HVAC System				
Central AC: ☑ Yes ☐ No				
Central heat: ☑ Yes ☐ No				
If not central heat, indicate <b>primary</b> heat source and fuel type:				
Are the heating, ventilation and air conditioning systems in good work	ing order? ☑ Yes ☐ No (explain)			
Date of last HVAC servicing/inspection: 11/01/2018				
Hazards Present				
Wood burning stove or central gas fireplace <i>not</i> professionally installed	? ☐ Yes ☑ No			
Space heater used as primary heat source? ☐ Yes ☑ No				
Is the source portable? ☐ Yes ☑ No				
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?				
Supplemental Information				
Age of system: 5 years				
Year last updated: 2018	towards plate)			
(Please attach photo(s) of HVAC equipment, including dated manufact	urer's piate)			
Plumbing System				
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No				
Is there any indication of an active leak? ☐ Yes ☑ No				
Is there any indication of a prior leak? ☐ Yes ☑ No				
Water heater location: Garage				
General condition of the following plumbing fixtures and connections to applicances:				
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A			
Dishwasher ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Toilets   ☑			
Washing Machine ☑ ☐ ☐	Sump pump			
Water Heater ☑ ☐	Main shut off valve ☑ ☐ ☐			
Showers/Tubs □ □	All other visible □ □ ☑			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: Type of pipes (check all that apply)				
X Original to home				
Completely re-piped ☑ PVC/CPVC				
Partially re-piped Galvanized				
(Provide year and extent of renovation in the comments below)				
□ Polybutylene				
	☐ Other (specify)			

<b>Roof</b> (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i> )					
Predominant Roof Secondary Roof					
Covering material: Clay Tile			Covering material: Modified Bitumen		
Roof age (years): 1			oof age (years): <u>25</u>		
Remaining useful life (years): 34			Remaining useful life (years): 0		
Date of last roofing permit: 06/30/2022  Date of last update: 06/30/2022	<u>'</u>		Date of last roofing permit: 03/27/1998		
If updated (check one):		If updated (check one):	Date of last update: 03/27/1998		
ii apaatea (eneek one).		ii apaatea (cheek one).			
☑ Full Replacement		☑ Full Replacement	☑ Full Replacement		
☐ Partial Replacement		☐ Partial Replacement	☐ Partial Replacement		
% of replacement		% of replacement	% of replacement		
Overall condition:		Overall condition:			
☑ Satisfactory		<b>☑</b> Satisfactory	☑ Satisfactory		
☐ Unsatisfactory (explain below)		☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)		
Any visible signs of damage / deterio	ration?	Any visible signs of damage / deteri	oration?		
(check all that apply and explain below)	(check all that apply and explain below) (check all that apply ar		and explain below)		
☐ Cracking		☐ Cracking			
☐ Cupping/Curling		☐ Cupping/Curling			
☐ Excessive granule loss			☐ Excessive granule loss		
$\square$ Exposed asphalt		☐ Exposed asphalt			
_ ` `		, , ,			
☐ Exposed felt		· ·	☐ Exposed felt		
☐ Missing/loose/cracked tabs or tiles	3		☐ Missing/loose/cracked tabs or tiles		
☐ Soft spots in decking	☐ Soft spots in decking		☐ Soft spots in decking		
☐ Visible hail damage	☐ Visible hail damage		$\square$ Visible hail damage		
☐ No roof cover		<b>☑</b> Water Ponding			
☐ Wood rot	Nood rot		☐ Granule Loss		
☐ Water Ponding		Any visible signs of leaks ☐ Yes ☑	Any visible signs of leaks ☐ Yes ☑ No		
□ Debri	□ Dehri		Attic/underside of decking ☐ Yes ☑ No		
☐ Granule Loss		Interior ceilings ☐ Yes ☑ No	Interior ceilings ☐ Yes ☑ No		
Any visible signs of leaks ☐ Yes ☑	No				
Attic/underside of decking ☐ Yes ☑ No					
Interior ceilings ☐ Yes ☑ No					
Additional Comments/Observ	ations(use additional pa	ages if needed):			
All 4-Point Inspection Formsmust be co	npleted and signed by a verifi	able Florida-licensed inspector.			
I certify that the above statements are true and correct.					
Nostandy Gonzalez	Home Inspector	HI14832	02/17/2023		
Inspector Signature	Title	License Number	Date		
South Florida Inspectors	Home Inspector	786-218-2844	_		
Company Name	License Type	Work Phone			

**Special Instructions:** This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### **Documenting the Condition of Each System**

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### **Note to All Agents**

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.


# **Photos, Additional Comments or Observations**


## **Exterior Photos**




**Electrical System** 


Panel Photos











# **HVAC System**

HVAC Equipment








## **Plumbing System**

Water Heater






Under cabinet plumbing & drains












**Exposed Valves** 





## Roof

Photos of Each Slope

