4-Point Inspection Form		
Insured/Applicant Name: Canterbury at Aberdeen Condo Assoc.	Application / Policy #:	
Address Inspected: 8042 Aberdeen Dr, Boynton Beach, FL 33472		
Actual Year Built: 1997	Date Inspected: 03/06/2023	
Minimum Photo Requirements ☑ Dwelling: Each side ☑ Roof: Each slope ☑ Plumbing: Water heater, u ☑ Main electrical service panel with interior door label ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-licensed inspector must	under cabinet plumbing/drains, exposed valves complete, sign and date this form.	
L		
Be advised that Underwriting will rely on the information in this sample form your choice. This information only is used to determine insurability and is no systems inspected.		
Electrical System Separate documentation of any aluminum wiring remediation must be provided.	ded and certified by a licensed electrician.	
Main Panel	Second Panel	
Type: ☑ Circuit breaker ☐ Fuse	Type: ☑ Circuit breaker ☐ Fuse	
Total Amps: 150 Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)	Total Amps: 150 Is amperage sufficient for current usage? ✓ Yes ☐ No (explain)	
Indicate presence of any of the following:		
☐ Cloth wiring		
☐ Active knob and tube		
☐ Branch circuit aluminum wiring (If present, describe the usage of all al	uminum wiring):	
* If single strand (aluminum branch) wiring, provide details of all remediation		
☐ Connections repair via COPALUM crimp	, ,	
☐ Connections repair via AlumniConn		
Hazards Present	☐ Double taps	
☐ Blowing fuses	☐ Exposed wiring	
☐ Tripping breakers	☐ Unsafe wiring	
☐ Empty sockets	☐ Improper breaker size	
☐ Loose Wiring	□ Scoring	
☐ Improper grounding	☐ Other (explain)	
☐ Over fusing		
General condition of the electrical system: ✓ Satisfactory Unsatisfactory	ctory (explain)	
Supplemental information		

Second Panel

Panel age: 2010

Year last updated: 2010

Brand/Model: General Electric

Wiring Type

☑ NM, BX or Conduit

☑ Copper

South Florida Inspectors 03/06/2023

Main Panel

Panel age: <u>1997</u>

Year last updated: 1997

Brand/Model: General Electric

4-Point Inspection Form

HVAC System				
Central AC: ☑ Yes ☐ No				
Central heat: ☑ Yes ☐ No				
If not central heat, indicate primary heat source and fuel type:				
Are the heating, ventilation and air conditioning systems in good working	order? ☑ Yes ☐ No (explain)			
Date of last HVAC servicing/inspection: 02/01/2022				
Hazards Present				
Wood burning stove or central gas fireplace not professionally installed?	Yes ☑No			
Space heater used as primary heat source? ☐ Yes ☑ No				
Is the source portable? ☐ Yes ☑ No				
Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?				
Supplemental Information				
Age of system: 1 year				
Year last updated: 2022	do plato)			
(Please attach photo(s) of HVAC equipment, including dated manufacture	s piate)			
Plumbing System				
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No				
Is there any indication of an active leak? ☐ Yes ☑ No				
Is there any indication of a prior leak? ☐ Yes ☑ No				
Water heater location: Garage				
General condition of the following plumbing fixtures and connections to applicances:				
Satisfactory Unsatisfactory N/A	Satisfactory Unsatisfactory N/A			
Dishwasher ☑ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐	Toilets			
Washing Machine ☑ □ □	Sump pump			
Water Heater □ □	Main shut off valve ☐ ☐			
Showers/Tubs	All other visible			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: Type of pipes (check all that apply)				
X Original to home				
Completely re-piped ☑ PVC/CPVC				
Partially re-piped Galvanized				
(Provide year and extent of renovation in the comments below)				
	Polybutylene			
	Other (specify)			

4-Point Inspection Form

Roof (With photos of each roof slope, this section can take the place of the <i>Roof Inspection Form.</i>)				
Predominant Roof Covering material: Clay Tile Roof age (years): 1 Remaining useful life (years): 34 Date of last roofing permit: 06/30/2022 Date of last update: 06/30/2022 If updated (check one):	<u></u>	Secondary Roof Covering material: Modified Bitumen Roof age (years): 25 Remaining useful life (years): 0 Date of last roofing permit: 12/17/1998 Date of last update: 12/17/1998 If updated (check one):		
☑ Full Replacement ☐ Partial Replacement % of replacement		☐ Full Replacement ☐ Partial Replacement % of replacement		
Overall condition:		Overall condition:		
☑ Satisfactory ☐ Unsatisfactory (explain below)		☑ Satisfactory ☐ Unsatisfactory (explain below)		
Any visible signs of damage / deterior (check all that apply and explain below a Cracking Cupping/Curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tile Soft spots in decking Visible hail damage No roof cover Wood rot Water Ponding Debri Granule Loss Any visible signs of leaks Yes Attic/underside of decking Yes Mo	es ÎNo	(check all that apply and explain below ☐ Cracking ☐ Cupping/Curling ☐ Excessive granule loss ☐ Exposed asphalt ☐ Exposed felt ☐ Missing/loose/cracked tabs or tile ☐ Soft spots in decking ☐ Visible hail damage ☑ Water Ponding ☐ Granule Loss Any visible signs of leaks ☐ Yes ☑	□ Cupping/Curling □ Excessive granule loss □ Exposed asphalt □ Exposed felt □ Missing/loose/cracked tabs or tiles □ Soft spots in decking □ Visible hail damage □ Water Ponding □ Granule Loss Any visible signs of leaks □ Yes ☑ No Attic/underside of decking □ Yes ☑ No	
Additional Comments/Observations(use additional pages if needed):				
All 4-Point Inspection Formsmust be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.				
Noslandy Gonzalez	Home Inspector	HI14832	02/18/2023	
Inspector Signature	Title	License Number	Date	
South Florida Inspectors	Home Inspector	786-218-2844	-	
Company Name	License Type	Work Phone	· ·	

4-Point Inspection Form

Special Instructions: This sample *4-Point Inspection Form*includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- Allhazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- · A general, residential, or building contractor
- · A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.

Photos, Additional Comments or Observations

Exterior Photos












Electrical System


Panel Photos











HVAC System


HVAC Equipment





Plumbing System

Water Heater



Under cabinet plumbing & drains





Exposed Valves





RoofPhotos of Each Slope



