4-Point Inspection Form					
Insured/Applicant Name:Canterbury at Aberdeen Condo Assoc.	Application / Policy #:				
Address Inspected: 8082 Aberdeen Dr, Boynton Beach, FL 33472					
Actual Year Built: 1997					
Minimum Photo Requirements					
Electrical System Separate documentation of any aluminum wiring remediation must be provided	led and certified by a licensed electrician.				
Main Panel         Type: ☑ Circuit breaker □ Fuse         Total Amps: 150         Is amperage sufficient for current usage? ☑ Yes □ No (explain)	Second Panel Type: ☑ Circuit breaker □ Fuse Total Amps: <u>150</u> Is amperage sufficient for current usage? ☑ Yes □ No (explain)				
Indicate presence of any of the following:   Cloth wiring  Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring):  * If single strand (aluminum branch) wiring, provide details of all remediation. <i>Separate documentation of all work must be provided.</i> Connections repair via COPALUM crimp Connections repair via AlumniConn					
Hazards Present	<ul> <li>Double taps</li> <li>Exposed wiring</li> <li>Unsafe wiring</li> <li>Improper breaker size</li> <li>Scoring</li> <li>Other (explain)</li> </ul>				

 Supplemental information

 Main Panel
 Second Panel
 Wiring Type

 Panel age: 1997
 Panel age: 2010
 Image: Copper

 Year last updated: 1997
 Year last updated: 2010
 Image: NM, BX or Conduit

 Brand/Model: General Electric
 Brand/Model: General Electric
 Image: Copper

South Florida Inspectors 03/06/2023

# **4-Point Inspection Form**

#### **HVAC System**

Central heat: ☑ Yes □ No

If not central heat, indicate primary heat source and fuel type: \_\_\_\_

Are the heating, ventilation and air conditioning systems in good working order? 🗹 Yes 🗌 No (explain)

Date of last HVAC servicing/inspection: 01/01/2017

#### Hazards Present

Wood burning stove or central gas fireplace*not*professionally installed? □ Yes ☑ No

Space heater used as primary heat source? ☐ Yes ☑ No

Is the source portable? ☐ Yes ☑ No

Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area?

Supplemental Information

Age of system: <u>6 years</u>

Year last updated: 2017

(Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)

Plumbing System					
Is there a temperature pressure relief valve on the water heater? ☑ Yes □ No Is there any indication of an active leak? □ Yes ☑ No Is there any indication of a prior leak? □ Yes ☑ No Water heater location:					
General condition of the following plumbing fixtures and connections	to applicances:				
Satisfactory Unsatisfactory N/A   Dishwasher Image: Constraint of the second se	Satisfactory Unsatisfactory N/A   Toilets Image: Constraint of the second secon				
Supplemental Information					
Age of Piping System: <u>X</u> Original to home Completely re-piped Partially re-piped (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply)            Copper             PVC/CPVC             Galvanized             PEX             Polybutylene             Other (specify)				

# **4-Point Inspection Form**

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)				
Predominant Roof	Secondary Roof			
Covering material: Clay Tile	Covering material: Modified Bitumen			
Roof age (years): 1	Roof age (years): 25			
Remaining useful life (years): <u>34</u>	Remaining useful life (years): 0			
Date of last roofing permit: 06/30/2022	Date of last roofing permit: 01/06/1999			
Date of last update: 06/30/2022	Date of last update: 01/06/1999			
If updated (check one):	If updated (check one):			
✓ Full Replacement	Full Replacement			
Partial Replacement	Partial Replacement			
% of replacement	% of replacement			
Overall condition:	Overall condition:			
☑ Satisfactory	☑ Satisfactory			
Unsatisfactory (explain below)	Unsatisfactory (explain below)			
Any visible signs of damage / deterioration?	Any visible signs of damage / deterioration?			
(check all that apply and explain below)	(check all that apply and explain below)			
□ Cracking	□ Cracking			
Cupping/Curling	Cupping/Curling			
Excessive granule loss	Excessive granule loss			
Exposed asphalt	Exposed asphalt			
Exposed felt	Exposed felt			
☐ Missing/loose/cracked tabs or tiles	☐ Missing/loose/cracked tabs or tiles			
$\Box$ Soft spots in decking	□ Soft spots in decking			
□ Visible hail damage	□ Visible hail damage			
□ No roof cover	☑ Water Ponding			
□ Wood rot	Granule Loss			
□ Water Ponding	Any visible signs of leaks 🗌 Yes 🗹 No			
☐ Debri	Attic/underside of decking Yes No			
Granule Loss	Interior ceilings 🗆 Yes 🗹 No			
Any visible signs of leaks □ Yes ☑ No				
Attic/underside of decking □ Yes ☑ No				
Interior ceilings I Yes I No				

Additional Comments/Obs	servations(use additional p	bages if needed):		
All 4-Point Inspection Formsmust b	, ,	fiable Florida-licensed inspector.		
I certify that the above statements	are true and correct.			
Noslandy Gonzalez	Home Inspector	HI14832	02/17/2023	
Inspector Signature	Title	License Number	Date	
South Florida Inspectors	Home Inspector	786-218-2844		
Company Name	License Type	Work Phone		

# **4-Point Inspection Form**

**Special Instructions:**This sample4-Point Inspection Formincludes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

#### **Photo Requirements**

Photos must accompany each4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- Roof: Each slope
- · Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- Electrical box with the panel off
- Allhazards or deficiencies

#### **Inspector Requirements**

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. Examples include:

- A general, residential, or building contractor
- A building code inspector
- A home inspector

*Note:* A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

#### Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

#### **Additional Comments or Observations**

This section of the 4-Point Inspection Formmust be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- · Any system determined not to be in good working order

#### Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.


# **Photos, Additional Comments or Observations**


**Exterior Photos** 




**Electrical System** 

Panel Photos








## **HVAC System**

### HVAC Equipment





# Plumbing System

Water Heater








Under cabinet plumbing & drains



Exposed Valves



# Roof

Photos of Each Slope



